



AUCTIM
ONLINE AUCTIONS

CATALOG PASSENGER CARS



DESCRIPTION

Passenger cars from various bankruptcies, seizures, breaches of contract, etc.

START

21 June 2022 to 08:00

END DATE

28 June 2022 from 17:00

VIEWING

- Wednesday June 22 2022 from 15:00 until 17:00
2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoен@auctim.be
BTW BE 0452.153.622

ISSUE - COLLECTION

- Wednesday July 06 2022 from 10:00 until 12:00
2630 Aartselaar, Helststraat 47

Online bidding only!


Catalog created on 28 June 2022 to 04:00

AUCTIM - MOYERSOEN NV

Helststraat 47
2630 Aartselaar, Belgium
VAT BE 0452.153.622

www.auctim.com
info.moyersoен@auctim.be



| | Item | Description | Start price |
|---|------|--|-------------|
|  | 457 | <p>Brand: SAAB Model: 9-3 Year of manufacture (yyyy): 2000 First registration (dd/mm/yyyy): 06/04/2000 Fuel: Gasoline + LPG Odometer reading (kms): UNKNOWN Chassis Number: YS3DF75T4Y7008495 Number of keys: 1 Vehicle category: M1: passenger car Car type: Berline Transmission: Manual transmission Displacement cc: 1985 Motor power kW: 113 Co2 emissions gr/km: 224 Exterior colour: Black Metallic color: No Color interior: Black Upholstery: Full leather Central locking: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Radio: Yes Seat heating: Yes Additional information: Only start with booster! Euro standard indefinite!</p> <p>Mileage on 13/06/2019: 237887 Certificate of registration: Yes, present Certificate of Conformity: Yes, present Test certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 01/07/2020 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p> | 188€ |



458


Brand: MINI
Model: MINI ONE
Version: D
Year of manufacture (yyyy): 2005
First registration (dd/mm/yyyy): 27/07/2005
Fuel: Diesel
Odometer reading (kms): 226073
Chassis Number: WMWRB11020TK40393
Number of keys: 2
Vehicle category: M1: passenger car
Car type: City car
Transmission: Manual transmission
Displacement cc: 1364
Motor power kW: 55
Emission class: Euro 3
Co2 emissions gr/km: 129
Exterior colour: Black
Metallic color: No
Color interior: Gray
Upholstery: Fabric
Air conditioning: Manual air conditioning
Central locking: Yes
Electric windows: Yes
Alloy Wheels: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Radio: Yes
Additional information: Only start with booster!
Suitcase won't open!
Certificate of registration: Yes, present
Certificate of Conformity: Yes, present
CARPASS: Yes, present
Test certificate: Yes, present
Inspection certificate valid until (dd/mm/yyyy)::
16/10/2021
Maintenance booklet: Not present
Visible vehicle damage: Yes, you can always
consult the photo report for a detailed overview of
the visible damage.
Vehicle damage description: Case won't open!
condition: Used
Quantity: 1

250€




| | | | |
|---|-----|---|--------|
|  | 461 | <p>Brand: VOLKSWAGEN Model: TOURAN Year of manufacture (yyyy): 2017 First registration (dd/mm/yyyy): 28/07/2017 Fuel gasoline Odometer reading (kms): 130741 Chassis number: WVGZZZ1TZH099270 Number of keys: 2 Vehicle category: M1: passenger car Car type: SUV or 4x4 Transmission: Automatic transmission Displacement cc: 1395 Motor power kW: 110 Emission class: Euro 6b Co2 emissions gr/km: 126 Exterior colour: Gray Metallic color: No Color interior: Gray Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: DAB radio Certificate of registration: Yes, present Certificate of Conformity: Yes, present Test certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 28/07/2022 Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo</p> | 3.000€ |
|---|-----|---|--------|




| | | | |
|---|-----|---|------|
| | | report. condition: Used Quantity: 1 | |
|  | 462 | Brand: BMW Model: X3 Year of manufacture (yyyy): 2007 First registration (dd/mm/yyyy): 26/09/2007 Fuel: Diesel Odometer reading (kms): 183154 Chassis Number: WBAPE110X0WH28121 Number of keys: 2 Vehicle category: M1: passenger car Car type: SUV or 4x4 Transmission: Manual transmission Displacement cc: 1995 Motor power kW: 120 Emission class: Euro 4 Co2 emissions gr/km: 172 Exterior colour: Beige Metallic color: No Color interior: Black Upholstery: Part leather Air conditioning: Fully automatic air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Towbar: Yes Seat heating: Yes Certificate of registration: Yes, present Certificate of Conformity: Yes, present Test certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 26/09/2022 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of | 625€ |




| | | | |
|---|-----|---|--------|
| | | the visible damage. Vehicle damage description: rear left bumper wheel arch condition: Used Quantity: 1 | |
|  | 471 | Brand: BMW Model: 630i Version: Gran Turismo Year of manufacture (yyyy): 2018 First registration (dd/mm/yyyy): 12/04/2018 Fuel gasoline Odometer reading (kms): 80566 Chassis Number: WBAJV21010BH92163 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Displacement cc: 1998 Motor power kW: 190 Emission class: Euro 6 Co2 emissions gr/km: 148 Exterior colour: Gray Metallic color: Yes Color interior: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes LED lighting: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes | 7.875€ |



| | | | |
|---|-----|--|--------|
| | | <p>Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports package: Yes Sports seats: Yes Towbar: Yes Other options: electric seats with memory function 360° camera DAB tuner electrically folding towbar Certificate of registration: Yes, present Certificate of Conformity: Yes, present Test certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 12/04/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: 1 deep scratch on the door condition: Used Quantity: 1</p> | |
|  | 475 | <p>Brand: VOLKSWAGEN Model: T-CROSS Version: LIFE 1.0L TSI Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 29/04/2021 Fuel gasoline Odometer reading (kms): 12350 Chassis number: WVGZZZC1ZMY052513 Number of keys: 2 Vehicle category: M1: passenger car Car type: Break / station wagon Transmission: Manual transmission Displacement cc: 999 Motor power kW: 70 Emission class: Euro 6 Co2 emissions gr/km: 110</p> | 4.000€ |




| | | | |
|---|-----|---|--------|
| | | <p>Exterior colour: Black Metallic color: Yes Color interior: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: DAB tuner Adaptive Cruise Control Certificate of registration: Yes, present Certificate of Conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. condition: Used Quantity: 1</p> | |
|  | 476 | <p>Brand: AUDIA Model: A5 Version: SPORTBACK S-LINE 40 TFSI Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 16/10/2020 Fuel: Hybrid - Electric/Petrol Odometer reading (kms): 33555 Chassis number: WAUZZZF53MA005999 Number of keys: 2 Vehicle category: M1: passenger car</p> | 9.000€ |




| | | | |
|--|--|--|--|
| | | <p>Car type: Berline Transmission: Automatic transmission Displacement cc: 1984 Motor power kW: 150 Emission class: Euro 6 Co2 emissions gr/km: 136 Exterior colour: Black Metallic color: Yes Color interior: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes LED lighting: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Sports seats: Yes Seat heating: Yes Other options: S-LINE VIRTUAL COCKPIT Certificate of registration: Yes, present Certificate of Conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. condition: Used Quantity: 1</p> | |
|--|--|--|--|




| | | | |
|---|-----|---|--------|
|  | 477 | <p>Brand: MERCEDES Model: A180 Version: D Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 28/05/2019 Fuel: Diesel Odometer reading (kms): 47463 Chassis Number: WDD1771031W005264 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Displacement cc: 1461 Motor power kW: 85 Emission class: Euro 6 Exterior colour: Black Metallic color: Yes Color interior: Black Upholstery: Part leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports seats: Yes Certificate of registration: Yes, present Certificate of Conformity: Yes, present CARPASS: Yes, present Test certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 28/05/2023 Maintenance booklet: Not present</p> | 4.000€ |
|---|-----|---|--------|




| | | | |
|---|-----|---|--------|
| | | <p>Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: front logo broken condition: Used Quantity: 1</p> | |
|  | 479 | <p>Brand: VOLKSWAGEN Model: TIGUAN Version: 2.0 TDI 150 DSG7 CONFORTLINE BUSINESS Year of manufacture (yyyy): 2016 First registration (dd/mm/yyyy): 15/11/2016 Fuel: Diesel Odometer reading (kms): 145812 Chassis Number: WVGZZZ5NZHW843105 Number of keys: 2 Vehicle category: M1: passenger car Car type: SUV or 4x4 Transmission: Automatic transmission Displacement cc: 1968 Motor power kW: 110 Emission class: Euro 6 Co2 emissions gr/km: 127 Exterior colour: Gray Metallic color: Yes Color interior: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes</p> | 4.375€ |




| | | | |
|--|------------|--|---------------|
| | | <p>Additional information: French registration certificate + customs document E705 present Certificate of registration: Yes, present Certificate of Conformity: Not present. (Import within European Union) Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: door frames condition: Used Quantity: 1</p> | |
|  | <p>480</p> | <p>Brand: VOLKSWAGEN Model: CADDY Version: LIFE Year of manufacture (yyyy): 2012 First registration (dd/mm/yyyy): 16/04/2013 Fuel: Diesel Odometer reading (kms): 433039 Chassis Number: WV2ZZZ2KZDX061293 Number of keys: 2 Vehicle category: M1: passenger car Car type: Break / station wagon Transmission: Manual transmission Displacement cc: 1598 Motor power kW: 55 Emission class: Euro 5 Co2 emissions gr/km: 149 Exterior colour: Black Metallic color: No Color interior: Black Upholstery: Fabric Air conditioning: Semi-automatic air conditioning On-board computer: Yes Central locking: Yes Electric windows: Yes Fog lights: Yes Radio: Yes Other options: vehicle suitable for the transport of disabled people, ramp available</p> | <p>1.000€</p> |




| | | | |
|--|-----|---|--------|
| | | <p>spare wheel available Certificate of registration: Yes, present Certificate of Conformity: Yes, present Test certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 18/04/2021 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various damage condition: Used Quantity: 1</p> | |
|  | 481 | <p>Brand: AUDIA Model: A3 Version: SPORTBACK 35 TDI 150 S-TRONIC 7 Year of manufacture (yyyy): 2018 First registration (dd/mm/yyyy): 05/07/2018 Fuel: Diesel Odometer reading (kms): 212970 Chassis Number: WAUZZZ8V8JA135821 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Displacement cc: 1968 Motor power kW: 110 Emission class: Euro 6 Co2 emissions gr/km: 112 Exterior colour: White Metallic color: No Color interior: Gray Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes</p> | 3.500€ |




| | | | |
|---|------------|---|---------------|
| | | <p>Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Shift paddles: Yes Additional information: French registration certificate + customs document E705 present! Certificate of registration: Yes, present Certificate of Conformity: Not present. (Import within European Union) Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. condition: Used Quantity: 1</p> | |
|  | <p>482</p> | <p>Brand: VOLKSWAGEN Model: PASSAT Year of manufacture (yyyy): 2011 First registration (dd/mm/yyyy): 09/01/2013 Fuel: Diesel Odometer reading (kms): 212752 Chassis number: WVWZZZ3CZBP345471 Number of keys: 4 Vehicle category: M1: passenger car Car type: Berline Transmission: Manual transmission Displacement cc: 1598 Motor power kW: 77 Emission class: Euro 5 Exterior colour: Black Metallic color: No Color interior: Gray Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes</p> | <p>1.250€</p> |



| | | | |
|---|-----|---|--------|
| | | <p>Cruise control: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Certificate of registration: Yes, present Certificate of Conformity: Yes, present Test certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 26/10/2022 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p> | |
|  | 483 | <p>Brand: BMW Model: 418D Version: 150 CH BUSINESS Year of manufacture (yyyy): 2017 First registration (dd/mm/yyyy): 16/10/2017 Fuel: Diesel Odometer reading (kms): 193970 Chassis Number: WBA4K11070BB99536 Number of keys: 2 Vehicle category: M1: passenger car Car type: Coupe Transmission: Manual transmission Displacement cc: 1995 Motor power kW: 110 Emission class: Euro 6 Co2 emissions gr/km: 109 Exterior colour: Gray Metallic color: Yes Color interior: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning</p> | 3.500€ |




| | | | |
|---|------------|--|---------------|
| | | <p>On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports seats: Yes Seat heating: Yes Additional information: French registration certificate + customs document E705 present! Certificate of registration: Yes, present Certificate of Conformity: Not present. (Import within European Union) Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p> | |
|  | <p>484</p> | <p>Brand: VOLKSWAGEN Model: TIGUAN Version: 2.0 TDI 150 DSG7 CONFORTLINE BUSINESS Year of manufacture (yyyy): 2018 First registration (dd/mm/yyyy): 20/09/2018 Fuel: Diesel Odometer reading (kms): 177022 Chassis number: WVGZZZ5NZJW457357 Number of keys: 2 Vehicle category: M1: passenger car Car type: SUV or 4x4 Transmission: Automatic transmission Displacement cc: 1968</p> | <p>5.250€</p> |




Motor power kW: 110
Emission class: Euro 6
Co2 emissions gr/km: 127
Exterior colour: Blue
Metallic color: Yes
Color interior: Black
Upholstery: Full leather
Reversing camera: Yes
Air conditioning: Fully automatic air conditioning
On-board computer: Yes
Central locking: Yes
Cruise control: Yes
Electric folding mirrors: Yes
Electric windows: Yes
Electric seats: Yes
Alloy Wheels: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Open roof: Yes
Panoramic roof: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Shift paddles: Yes
Sports seats: Yes
Towbar: Yes
Seat heating: Yes
Other options: electric seats with memory function
Additional information: French registration certificate + customs document E705 present!
Certificate of registration: Yes, present
Certificate of Conformity: Not present. (Import within European Union)
Test certificate: Not present
Maintenance booklet: Not present
Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report.
condition: Used
Quantity: 1



| | | | |
|---|-----|--|--------|
| | | | |
|  | 485 | <p>Brand: VOLKSWAGEN Model: TOURAN Version: 2.0TDI 150 BMT DSG6 7PL R-LINE Year of manufacture (yyyy): 2018 First registration (dd/mm/yyyy): 04/07/2018 Fuel: Diesel Odometer reading (kms): 197917 Chassis number: WVGZZZ1TZJW107498 Number of keys: 2 Vehicle category: M1: passenger car Car type: Mono volume Transmission: Automatic transmission Displacement cc: 1968 Motor power kW: 110 Emission class: Euro 6 Co2 emissions gr/km: 122 Exterior colour: White Metallic color: No Color interior: Gray Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports seats: Yes Other options: R-LINE 7 seats Additional information: French registration certificate + customs document E705 present! Certificate of registration: Yes, present</p> | 4.250€ |




| | | | |
|---|-----|---|--------|
| | | <p>Certificate of Conformity: Not present. (Import within European Union) Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various damage condition: Used Quantity: 1</p> | |
|  | 486 | <p>Brand: BMW Model: X3 Year of manufacture (yyyy): 2016 First registration (dd/mm/yyyy): 08/06/2016 Fuel: Diesel Odometer reading (kms): 134475 Chassis Number: WBAWZ310300R75556 Number of keys: 2 Vehicle category: M1: passenger car Car type: SUV or 4x4 Transmission: Automatic Transmission Displacement cc: 1995 Motor power kW: 110 Emission class: Euro 6b Exterior colour: Black Metallic color: Yes Color interior: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric tailgate: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes</p> | 4.000€ |



| | | | |
|---|-----|--|--------|
| | | <p>Radio: Yes Shift paddles: Yes Sports package: Yes Sports seats: Yes Seat heating: Yes Other options: M package</p> <p>Additional information: Tire pressure monitoring failed, flat tire front right Certificate of registration: Yes, present Certificate of Conformity: Yes, present Identification Report: Yes, Present Test certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 11/10/2022 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: front left bumper condition: Used Quantity: 1</p> | |
|  | 488 | <p>Brand: AUDIA Model: A3 Version: SPORTBACK Year of manufacture (yyyy): 2014 First registration (dd/mm/yyyy): 25/03/2014 Fuel: Diesel Odometer reading (kms): 112531 Chassis Number: WAUZZZ8VXEA152853 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Displacement cc: 1968 Motor power kW: 110 Emission class: Euro 5b Co2 emissions gr/km: 119 Exterior colour: Brown Metallic color: Yes Color interior: Beige</p> | 2.500€ |





| | | | |
|---|-----|--|--------|
| | | <p>Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Electric seats: Yes Alloy Wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Open roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports seats: Yes Seat heating: Yes Certificate of registration: Yes, present Certificate of Conformity: Yes, present Identification Report: Yes, Present Test certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 25/03/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p> | |
|  | 489 | <p>Brand: CITROËN Model: C4 Version: SPACE TOURER Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 24/07/2019 Fuel gasoline Odometer reading (kms): 14909 Chassis Number: VF73EHNSRKJ718066 Number of keys: 2 Vehicle category: M1: passenger car</p> | 4.000€ |



| | | | |
|--|--|--|--|
| | | <p>Car type: Mono volume Transmission: Automatic transmission Displacement cc: 1199 Motor power kW: 96 Emission class: Euro 6 Exterior colour: Gray Metallic color: Yes Color interior: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Alloy Wheels: Yes Massage chairs: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Certificate of registration: Yes, present Certificate of Conformity: Yes, present Test certificate: Not present Maintenance booklet: Yes, Present Maintenance performed by: SA GARAGE PIGEON Last maintenance dd/mm/yyyy: 14/07/2020 Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: tank lid no longer closes rear bumper right scratch condition: Used Quantity: 1</p> | |
|--|--|--|--|



| | | | |
|---|-----|---|------|
|  | 493 | <p>Brand: NISSAN Model: MICRA Year of manufacture (yyyy): 1998 First registration (dd/mm/yyyy): 07/07/1999 Fuel gasoline Odometer reading (kms): 200464 Chassis number: SJNEBAK11U3000966 Number of keys: 1 Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Displacement cc: 1275 Motor power kW: 55 Exterior colour: Gray Metallic color: No Color interior: Gray Upholstery: Fabric Electric windows: Yes Radio: Yes Towbar: Yes Certificate of registration: Yes, present Certificate of Conformity: Yes, present CARPASS: Yes, present Test certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 16/04/2022 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various damage condition: Used Quantity: 1</p> | 125€ |
|  | 494 | <p>Brand: FORD Model: KA Year of manufacture (yyyy): UNKNOWN First registration (dd/mm/yyyy): UNKNOWN Fuel: UNKNOWN Odometer reading (kms): UNKNOWN Chassis Number: WF0BXXWPRBYG15025 Number of keys: 0</p> | 125€ |



| | | | |
|--|--|---|--|
| | | <p>Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Exterior colour: Gray Metallic color: No Color interior: Gray Upholstery: Fabric Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Radio: Yes Additional information: NO BOARD DOCUMENTS/ KEY AVAILABLE! Registration certificate: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Not present: the buyer receives a certificate of loss of certificate of conformity Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: NO BOARD DOCUMENTS / KEY PRESENT! condition: Used Quantity: 1</p> | |
|--|--|---|--|