

CATALOG PASSENGER CARS



DESCRIPTION

Passenger cars from various bankruptcies, seizures, breaches of contract, etc.

START

14 march 2023 to 09:00 [UTC]

END DATE

21 march 2023 from 18:00 [UTC]

VIEWING

- Wednesday March 15 2023 from 15:00 until 17:00
Helststraat 47, 2630 Aartselaar

AUCTIM PARTNER

MOYERSOEN NV



Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoен@auctim.be
BTW BE 0452.153.622

ISSUE - COLLECTION

- Wednesday March 29 2023 from 10:00 until 12:00
Helststraat 47, 2630 Aartselaar

Online bidding only!


Catalog created on 21 march 2023 to 04:00

	Item	Description	Start price
	1	<p>Sell yourself? Click here!</p> <p>Via online auctions on the Auctim platform you immediately get value for your money. Or better, money for your money!</p> <ul style="list-style-type: none"> • Our partners look at the possibilities together with you • You benefit from an extensive, worldwide marketing campaign • Reach a buying audience from over 150 countries with millions of page views every month • You will receive the proceeds from your lots barely 20 days after the auction. <p>(Almost) convinced? Click here!</p>	1€
	2	<p>Brand: Audi Model: A5 Version: SPORTBACK S-LINE 40 TDI S-TRONIC Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 11/08/2022 Fuel: Diesel Odometer reading (km): 12021 Chassis number: WAUZZZF56NA035693 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Coupe Transmission: Automatic transmission Cylinder capacity cc: 1968 Motor power kW: 150 Emission class: Euro 6 Exterior colour: Black Metal Color: Yes Interior color: Black Upholstery: Partial leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes</p>	8.000€




		<p>Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes LED lighting: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Sports seats: Yes Towbar: Yes Seat heating: Yes Other options: S-LINE Electric seats with memory function Audi Virtual Cockpit Plus DAB tuner BANG & OLUFSEN premium sound system Mythos black metallic color Shadow look Adblue tank (24 litres) Matrix LED headlights with dynamic turn signals Red calipers Darkened side windows and rear window Mood lighting package Pack Business Plus Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No, except for general usage damage. (General use damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. condition: Used Quantity: 1</p>	
--	--	--	--




	3	<p>Make: MERCEDES BENZ Model: A 180 D Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 28/11/2018 Fuel: Diesel Odometer reading (km): 139686 Chassis number: WDD1770031J016427 Number of keys: 2 Vehicle category: M1: passenger car Type of car: Break / station wagon Transmission: Automatic transmission Cylinder capacity cc: 1461 Engine power kW: 85 Emission class: Euro 6 Exterior colour: Silver Metal Color: No Interior color: Black Upholstery: Partial leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports package: Yes Sports seats: Yes Seat heating: Yes Certificate of registration: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 12/01/2023 Maintenance booklet: Not present</p>	3.250€
---	---	--	--------




		<p>Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various minor damages condition: Used Quantity: 1</p>	
	4	<p>Brand: SKODA Model: OCTAVIA Year of construction (yyyy): 2014 First registration (dd/mm/yyyy): 06/01/2014 Fuel: Diesel Odometer reading (km): 259426 Chassis number: TMBJG7NEXE0071369 Number of keys: 2 Vehicle category: M1: passenger car Type of car: Break / station wagon Transmission: Automatic transmission Cylinder capacity cc: 1598 Engine power kW: 77 Emission class: Euro 5 Exterior colour: Silver Metal Color: No Interior color: Black Upholstery: Fabric On-board computer: Yes Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Seat heating: Yes Other options: DAB tuner Certificate of registration: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present</p>	1.000€




		<p>Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 28/06/2023 Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various minor damages condition: Used Quantity: 1</p>	
	5	<p>Brand: DACIA Model: LODGY Year of construction (yyyy): 2014 First registration (dd/mm/yyyy): 16/12/2014 Fuel: Diesel Odometer reading (km): 251400 Chassis number: UU1JSDBC651832779 Number of keys: 1 Vehicle category: M1: passenger car Type of car: Break / station wagon Transmission: Manual transmission Cylinder capacity cc: 1461 Engine power kW: 79 Emission class: Euro 5b Color exterior: Gray Metal Color: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise Control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Towbar: Yes Additional information: radio code unknown Certificate of registration: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Test certificate: Yes, present</p>	500€




		<p>Test certificate valid until (dd/mm/yyyy):: 19/05/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various damages condition: Used Quantity: 1</p>	
	9	<p>Brand: VOLVO Model: V40 Version: BLACK EDITION T2 GEARTRONIC Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 10/01/2019 Fuel gasoline Odometer reading (km): 190790 Chassis number: YV1MV33V0K2579642 Number of keys: 2 Vehicle category: M1: passenger car Type of car: Berline Transmission: Automatic transmission Cylinder capacity cc: 1498 Motor power kW: 90 Emission class: Euro 6 Co2 emissions gr/km: 156 Exterior colour: White Metal Color: No Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes</p>	1.750€




		<p>Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Yes, present Test certificate: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	
	<p>10</p>	<p>Brand: DACIA Model: DUSTER Version: SL RAINBOW BLUE DCI 115 4WD Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 20/05/2019 Fuel: Diesel Odometer reading (km): 124397 Chassis number: VF1HJD40862935733 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Manual transmission Cylinder capacity cc: 1461 Engine power kW: 85 Emission class: Euro 6 Co2 emissions gr/km: 152 Color exterior: Gray Metal Color: Yes Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes</p>	<p>2.188€</p>



		<p>Radio: Yes Towbar: Yes Certificate of registration: Yes, present Certificate of conformity: Not present: the buyer receives a certificate of loss of conformity certificate Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	
	11	<p>Make: MERCEDES BENZ Model: A200 Edition: LAUNCH EDITION Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 30/09/2019 Fuel gasoline Odometer reading (km): 154610 Chassis number: WDD1771871J154610 Number of keys: 0 Vehicle category: M1: passenger car Type of car: Berline Transmission: Automatic transmission Cylinder capacity cc: 1332 Motor power kW: 120 Emission class: Euro 6 Color exterior: Gray Metal Color: Yes Interior color: Black Upholstery: Partial leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes LED lighting: Yes</p>	2.500€




		<p>Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports package: Yes Sports seats: Yes Seat heating: Yes Other options: AMG package APPLE CAR PLAY ANDROID AUTO electric seats with memory function Additional information: no key present!! Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: no key present!! various damages! condition: Used Quantity: 1</p>	
	<p>13</p>	<p>Brand: BMW Model: X3 Version: SDRIVE18D Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 25/02/2021 Fuel: Diesel Odometer reading (km): 109339 Chassis number: WBAUZ15000N072807 Number of keys: 2 Vehicle category: M1: passenger car</p>	<p>5.000€</p>




		<p>Vehicle type: SUV or 4x4 Transmission: Automatic transmission Cylinder capacity cc: 1995 Engine power kW: 110 Emission class: Euro 6 Exterior colour: Black Metal Color: No Color interior: Beige Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Head-up display: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports package: Yes Sports seats: Yes Seat heating: Yes Other options: DAB tuner M package Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No, except for general usage damage. (General use damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. condition: Used</p>	
--	--	--	--





		Quantity: 1	
	16	<p>Brand: DACIA Model: DOKKER Version: ESSENTIAL BLUE DCI 95 Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 03/07/2020 Fuel: Diesel Odometer reading (km): 102957 Chassis number: UU1K6720165495137 Number of keys: 1 Vehicle category: M1: passenger car Type of car: Break / station wagon Transmission: Manual transmission Cylinder capacity cc: 1461 Motor power kW: 70 Emission class: Euro 6 Co2 emissions gr/km: 132 Exterior colour: White Metal Color: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Additional information: Various damage: mold spores, front bumper, leak Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: Various damages: mold spores, front bumper, leak. Various notifications dashboard.</p>	500€




		condition: Used Quantity: 1	
	17	Brand: DACIA Model: DOKKER Version: ESSENTIAL BLUE DCI 95 Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 30/07/2020 Fuel: Diesel Odometer reading (km): 72323 Chassis number: UU1K6720365495138 Number of keys: 1 Vehicle category: M1: passenger car Type of car: Break / station wagon Transmission: Manual transmission Cylinder capacity cc: 1461 Motor power kW: 70 Emission class: Euro 6 Co2 emissions gr/km: 132 Exterior colour: White Metal Color: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Rear parking sensors: Yes Radio: Yes Additional information: Mold spores Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: Mold spores condition: Used Quantity: 1	750€




	18	<p>Brand: JIAJUE Fashion model: . Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 19/06/2017 Fuel gasoline Odometer reading (km): 9504 Chassis number: LLPTCBA05G1L28200 Motorcycle Type: Scooter Transmission: Semi automatic transmission Emission class: Euro 2 Color exterior: not used Number of keys: 1 Number of seats: 2 Electric starter: Yes Additional information: Moped does not start! Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Not present: the buyer receives a certificate of loss of conformity certificate Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various damages moped does not start! condition: Used Quantity: 1</p>	38€
	19	<p>Brand: CITROEN Model: C3 Year of construction (yyyy): 2004 First registration (dd/mm/yyyy): 17/08/2004 Fuel gasoline Odometer reading (km): 228487 Chassis number: VF7FCHF XB27109300 Number of keys: 0 Vehicle category: M1: passenger car Type of car: City car</p>	50€




		<p>Transmission: Manual transmission Cylinder capacity cc: 1124 Engine power kW: 44 Emission class: Euro 3 Exterior colour: Red Metal Color: No Interior color: Black Upholstery: Fabric Central locking: Yes Radio: Yes Additional information: no key present! Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 10/09/2022 Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: no key present! various damages condition: Used Quantity: 1</p>	
	21	<p>Brand: MINI Model: COOPER Execution: D Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 25/07/2017 Fuel: Diesel Odometer reading (km): 215860 Chassis number: WMWXT310602B52794 Number of keys: 2 Vehicle category: M1: passenger car Type of car: City car Transmission: Manual transmission Cylinder capacity cc: 1496 Engine power kW: 85 Emission class: Euro 6b Co2 emissions gr/km: 95 Color exterior: Gray Metal Color: No</p>	1.500€



		<p>Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 25/07/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various minor damages condition: Used Quantity: 1</p>	
	22	<p>Brand: VOLVO Model: V50 Year of manufacture (yyyy): 2010 First registration (dd/mm/yyyy): 14/10/2010 Fuel: Diesel Odometer reading (km): 161416 Chassis number: YV1MW76F2B2609154 Number of keys: 2 Vehicle category: M1: passenger car Type of car: Break / station wagon Transmission: Manual transmission Cylinder capacity cc: 1560 Motor power kW: 80 Emission class: Euro 4 Co2 emissions gr/km: 104 Color exterior: Gray</p>	250€



		<p>Metal Color: No Color interior: Gray Upholstery: Fabric Air conditioning: Fully automatic air conditioning Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes Rear parking sensors: Yes Radio: Yes Additional information: brakes defective!! Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 22/01/2022 Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: brakes defective! crack in windshield! condition: Used Quantity: 1</p>	
	25	<p>Brand: SMART Model: FORTWO COUPE Year of manufacture (yyyy): 2016 First registration (dd/mm/yyyy): 04/03/2016 Fuel gasoline Odometer reading (km): 48381 Chassis number: WME4533421K018074 Number of keys: 2 Vehicle category: M1: passenger car Type of car: City car Transmission: Automatic transmission Cylinder capacity cc: 999 Engine power kW: 52 Emission class: Euro 6b Exterior colour: Silver Metal Color: No Interior color: Black Upholstery: Fabric</p>	1.250€



		<p>Air conditioning: Semi-automatic air conditioning Central locking: Yes Cruise Control: Yes Electric windows: Yes Alloy Wheels: Yes Multifunctional steering wheel: Yes Radio: Yes Certificate of registration: Yes, present Certificate of conformity: Not present: the buyer receives a certificate of loss of conformity certificate Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	
--	--	--	--