



CATALOG
COMMERCIAL VEHICLES



DESCRIPTION

Commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

21 march 2023 to 09:00 [UTC]

END DATE

28 march 2023 from 16:00 [UTC]

VIEWING

- Wednesday March 22 2023 from 15:00 until 17:00
Helststraat 47, 2630 Aartselaar
- Friday March 24 2023 from 14:00 until 15:00
Helststraat 47, 2630 Aartselaar

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoен@auctim.be
BTW BE 0452.153.622



ISSUE - COLLECTION

- Wednesday April 05 2023 from 10:00 until 12:00
Helststraat 47, 2630 Aartselaar


Online bidding only!

Catalog created on 28 march 2023 to 04:00




	Item	Description	Start price
	1	<p>Sell yourself? Click here!</p> <p>Via online auctions on the Auctim platform you immediately get value for your money. Or better, money for your money!</p> <ul style="list-style-type: none">• Our partners look at the possibilities together with you• You benefit from an extensive, worldwide marketing campaign• Reach a buying audience from over 150 countries with millions of page views every month• You will receive the proceeds from your lots barely 20 days after the auction. <p>(Almost) convinced? Click here!</p>	1€
	7	<p>Brand: CITROEN Model: JUMPER Year of construction (yyyy): 2014 First registration (dd/mm/yyyy): 09/04/2014 Fuel: Diesel Odometer reading (km): 123407 Chassis number: VF7YBTMFB12569619 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowed Mass (kg): 3300 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 96 Emission class: Euro 5b Co2 emissions gr/km: 199 Exterior colour: White Metal Color: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning</p>	2.250€




		<p>Central locking: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Other options: Including lock GARMIN navigation Certificate of registration: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 14/04/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: Crack in the windshield Wing mirror Cover plate condition: Used Quantity: 1</p>	
	14	<p>Brand: FIAT Model: DOBLO Version: CARGO Year of construction (yyyy): 2008 First registration (dd/mm/yyyy): 27/03/2008 Fuel: Diesel Odometer reading (km): 222713 Chassis number: ZFA22300005592647 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowed Mass (kg): 2180 Transmission: Manual transmission Cylinder capacity cc: 1910 Engine power kW: 77 Emission class: Euro 4</p>	375€




		<p>Exterior colour: White Metal Color: No Interior color: Black Upholstery: Fabric Electric windows: Yes Fog lights: Yes Rear parking sensors: Yes Radio: Yes Other options: roof rack Certificate of registration: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 03/02/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: cracks in the windshield rust formation condition: Used Quantity: 1</p>	
	15	<p>Make: MERCEDES BENZ Model: VITO Version: 119 CDI Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 04/01/2018 Fuel: Diesel Odometer reading (km): 241369 Chassis number: WDF44760313407379 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowed Mass (kg): 2800 Transmission: Automatic transmission Cylinder capacity cc: 2143 Engine power kW: 140 Emission class: Euro 6b</p>	2.250€




		<p>Co2 emissions gr/km: 154 Color exterior: Gray Metal Color: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Cruise Control: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 24/04/2021 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various damages! condition: Used Quantity: 1</p>	
	16	<p>Brand: CITROEN Model: JUMPER Year of construction (yyyy): 2014 First registration (dd/mm/yyyy): 25/03/2014 Fuel: Diesel Odometer reading (km): 109948 Chassis number: VF7YBTMFB12569779 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowed Mass (kg): 3300</p>	2.000€




		<p>Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 96 Emission class: Euro 5b Co2 emissions gr/km: 199 Exterior colour: White Metal Color: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Additional information: start with booster! Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 14/04/2023 Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: start with booster! windshield cracked various damages condition: Used Quantity: 1</p>	
	18	<p>Brand: CITROEN Model: JUMPER Execution: L2H2 2.2 Year of construction (yyyy): 2008 First registration (dd/mm/yyyy): 11/03/2008 Fuel: Diesel Odometer reading (km): 179446 Chassis number: VF7YBBMFB11385227 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van</p>	625€



		<p>Number of axles: 2 Maximum Allowed Mass (kg): 3300 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 88 Emission class: Euro 4 Exterior colour: White Metal Color: No Interior color: Black Upholstery: Fabric Central locking: Yes Electric windows: Yes Fog lights: Yes Radio: Yes Towbar: Yes Other options: GARMIN navigation Certificate of registration: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 24/08/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: side mirror glass, rust formation, cover plate condition: Used Quantity: 1</p>	
	20	<p>Brand: FIAT Model: FIORINO Year of manufacture (yyyy): 2015 First registration (dd/mm/yyyy): 20/03/2015 Fuel: Diesel Odometer reading (km): 188864 Chassis number: ZFA22500006A02919 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van</p>	750€



		<p>Number of axles: 2 Maximum Allowed Mass (kg): 1700 Transmission: Manual transmission Cylinder capacity cc: 1248 Engine power kW: 55 Emission class: Euro 5b Co2 emissions gr/km: 119 Exterior colour: Silver Metal Color: No Interior color: Black Upholstery: Fabric Fog lights: Yes Rear parking sensors: Yes Radio: Yes Other options: PARROT car kit Certificate of registration: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 26/03/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: crack in windshield various minor damages condition: Used Quantity: 1</p>	
	52	<p>Brand: VSN Model: VSN21 Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 11/05/2021 Chassis number: VF9S13VKB20530519 Number of keys: 4+1 Construction: food truck Number of Axes: 1 Maximum Allowed Mass (kg): 1350 Exterior colour: White Color interior: White Additional information: Equipped with:</p>	1.125€



		<p>1x saladette with glass housing SARO 323-1030, 1200x400xH440mm 1x 3-door refrigerated workbench, 2200x560xH860mm 2x electric soup kettles DMCHEF 10L 1x heating element DOMO 1x DOMO microwave oven 1x cooker hood DANLIQI 1x manual extendable awning 1x small cash drawer 4x sliding windows 1x sink with faucet, 370x320mm 2x roll-out billboards 1x stool 1x stainless steel shelf 1x wooden billboard 7x sockets internally and 2x externally 1x electric cable</p> <p>Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	
--	--	---	--