

CATALOG
PASSENGER CARS



DESCRIPTION

Auction of various passenger cars from various bankruptcies, seizures, breaches of contract, etc.

START

12 september 2023 to 08:00 [UTC]

END DATE

19 september 2023 from 17:00 [UTC]

VIEWING

- Wednesday September 13 2023 from 15:00 until 17:00
Helststraat 47, 2630 Aartselaar

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoem@auctim.be
BTW BE 0452 153 622



ISSUE - COLLECTION

- Wednesday September 27 2023 from 10:00 until 12:00
Helststraat 47, 2630 Aartselaar

Online bidding only!

Catalog created on 19 september 2023 to 04:01




	Item	Description	Start price
	1	<p>Sell yourself? Click here!</p> <p>Via online auctions on the Auctim platform you immediately get value for your money. Or better, money for your money!</p> <ul style="list-style-type: none">• Our partners look at the possibilities together with you• You benefit from an extensive, worldwide marketing campaign• Reach a buying audience from over 150 countries with millions of page views every month• You will receive the proceeds from your lots barely 20 days after the auction. <p>(Almost) convinced? Click here!</p>	100€
	2	<p>Brand: MASERATI Model: GHIBLI Version: GS 350 Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 15/04/2022 Fuel gasoline Read odometer reading (km): 46412 Chassis number: ZAMXS57B001377311 Number of keys: 1 Vehicle category: M1: passenger car Type of car: Berline Transmission: Automatic transmission Cylinder capacity cc: 2979 Engine power kW: 257 Emission class: Euro 6 Color exterior: Gray Metal Color: Yes Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes</p>	100€




		<p>Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes Electric seats: Yes LED lighting: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports package: Yes Sports seats: Yes Seat heating: Yes Other options: electric seats with memory function steering wheel heating HARMAN KARDON sound system DAB tuner Additional information: Including model car MASERATI GHIBLI Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various damages: rim damage, front bumper right, rear bumper left (DK) Car registration: The car is with Danish registration tax condition: Used Quantity: 1</p>	
--	--	---	--




	3	<p>Brand: ALFA ROMEO Model: STELVIO Version: 2.0 B-TECH Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 12/04/2019 Fuel gasoline Read odometer reading (km): 144753 Chassis number: ZARPAHBN2K7C38339 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Automatic transmission Cylinder capacity cc: 1995 Engine power kW: 206 Emission class: Euro 6 Co2 emissions g/km: 212 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports seats: Yes Seat heating: Yes Other options: electric seats with memory function steering wheel heating including 4 extra summer tires on original ALFA ROMEO rim</p>	100€
---	---	---	------



		<p>Additional information: The orange light is on because the winter tires are mounted, which do not have automatic tire pressure measurement. This is the case on summer tires. Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 06/07/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	4	<p>Make: MERCEDES BENZ Model: C180D Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 09-12-2019 Fuel: Diesel Read odometer reading (km): 103591 Chassis number: WDD2050001R553690 Number of keys: 1 Vehicle category: M1: passenger car Type of car: Berline Transmission: Automatic transmission Cylinder capacity cc: 1597 Motor power kW: 90 Emission class: Euro 6 Color exterior: Gray Metal Color: Yes Interior color: Black Upholstery: Partial leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electric windows: Yes Electric seats: Yes Alloy Wheels: Yes</p>	100€




		<p>Multifunctional steering wheel: Yes Navigation: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Xenon lighting: Yes Seat heating: Yes Additional information: seats in ARTICO man-made leather and black fabric Certificate of registration: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 09-12-2023 Maintenance booklet: Not present Visible vehicle damage: No, except for general usage damage. (General use damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. Invoice amount (€ incl. VAT): 26,950.00 Invoice date (dd-mm-yyyy): 12-03-2021 condition: Used Quantity: 1</p>	
	4	<p>Brand: PORSCHE Model: CAYENNE Version: TURBO Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 22/07/2021 Fuel gasoline Odometer reading (km): 69813 Chassis number: WP1ZZZ9YZMDA37152 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV / 4x4 Transmission: Automatic transmission Cylinder capacity cc: 3996 Engine power kW: 404 Emission class: Euro 6 Exterior colour: Black</p>	100€




		<p>Metal Color: Yes Specific factory color: JET BLACK METALLIC Color interior: Red Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Head-up display: Yes LED lighting: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports package: Yes Sports seats: Yes Seat ventilation: Yes Seat heating: Yes Other options: electric seats with memory function DAB tuner Bose sound system Sports exhaust pack carbon design 21" "SPYDER DESIGN" aluminum rims white disc brakes interior pack carbon lane change assistant Pack sports chrono surround view Darkened windows Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Not present</p>	
--	--	--	--




		Maintenance booklet: Not present Visible vehicle damage: No, except for general usage damage. (General use damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. condition: Used Quantity: 1	
	5	Brand: FIAT Model: 500 Execution: E Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 23/05/2022 Fuel: Electric Read odometer reading (km): 15427 Chassis number: ZFAEFAC44NX079199 Number of keys: 2 Vehicle category: M1: passenger car Type of car: City car Transmission: Automatic transmission Engine power kW: 87 Exterior colour: Green Metal Color: Yes Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning Central locking: Yes Cruise Control: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Panoramic roof: Yes Radio: Yes Seat heating: Yes Other options: DAB tuner Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate	100€




		<p>Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No, except for general usage damage. (General use damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. condition: Used Quantity: 1</p>	
	6	<p>Make: MERCEDES BENZ Model: A180 Execution: BUSINESS SOLUTION ESSENTIAL+ Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 28/04/2022 Fuel gasoline Read odometer reading (km): 22032 Chassis number: W1K1771841J354275 Number of keys: 2 Vehicle category: M1: passenger car Type of car: Berline Transmission: Automatic transmission Cylinder capacity cc: 1332 Motor power kW: 100 Emission class: Euro 6 Color exterior: Gray Metal Color: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes</p>	100€




		<p>Front parking sensors: Yes Radio: Yes Seat heating: Yes Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No, except for general usage damage. (General use damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. condition: Used Quantity: 1</p>	
	7	<p>Brand: BMW Model: 520D Year of manufacture (yyyy): 2010 First registration (dd/mm/yyyy): 29/06/2010 Fuel: Diesel Odometer reading (km): 433591 Chassis number: WBAFW11070C279777 Number of keys: 1 Vehicle category: M1: passenger car Type of car: Berline Transmission: Automatic transmission Cylinder capacity cc: 1995 Motor power kW: 120 Emission class: Euro 5 Exterior colour: Black Metal Color: No Color interior: Beige Upholstery: Full leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes</p>	100€




		<p>Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Additional information: start with booster! Certificate of registration: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 09/12/2022 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: start with booster! notification dashboard condition: Used Quantity: 1</p>	
	7	<p>Brand: Audi Model: A1 Version: CITYCARVER 25TFSI Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 28/06/2021 Fuel gasoline Read odometer reading (km): 36024 Chassis number: WAUZZZGB2LR054812 Number of keys: 1 Vehicle category: M1: passenger car Type of car: City car Transmission: Manual transmission Cylinder capacity cc: 999 Motor power kW: 70 Emission class: Euro 6 Co2 emissions gr/km: 119 Exterior colour: Black Metal Color: Yes Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes</p>	100€




		<p>Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: virtual cockpit Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No, except for general usage damage. (General use damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. condition: Used Quantity: 1</p>	
	8	<p>Brand: AIXAM Model: CITY GTO Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 27/08/2021 Fuel: Diesel Read odometer reading (km): 8877 Chassis number: VLGUV53DFA3222147 Number of keys: 1 Vehicle category: M1: passenger car Type of car: City car Transmission: Automatic transmission Cylinder capacity cc: 479 Motor power kW: 6 Emission class: Euro 5 Exterior colour: White Metal Color: No Interior color: Black</p>	100€




		<p>Upholstery: Artificial leather Reversing camera: Yes Central locking: Yes Electric windows: Yes Alloy Wheels: Yes Rear parking sensors: Yes Radio: Yes Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	
	9	<p>Brand: VOLKSWAGEN Model: GOLF Version: GTI Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 18/02/2021 Fuel gasoline Read odometer reading (kms): 84493 Chassis number: WVVZZZCDZMW051124 Number of keys: 1 Vehicle category: M1: passenger car Type of car: City car Transmission: Automatic transmission Cylinder capacity cc: 1984 Motor power kW: 180 Exterior colour: Black Metal Color: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes</p>	100€




		<p>Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports package: Yes Seat heating: Yes Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various damages condition: Used Quantity: 1</p>	
	<p>9</p>	<p>Brand: PORSCHE Model: PANAMERA Version: TURBO Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 21/09/2011 Fuel gasoline Read odometer reading (kms): 77887 Chassis number: WP0ZZZ97ZCL080624 Number of keys: 2 + 1 Vehicle category: M1: passenger car Type of car: Berline Transmission: Automatic transmission Cylinder capacity cc: 4806 Engine power kW: 368 Emission class: Euro 5 Exterior colour: Black Metal Color: No Color interior: Beige Upholstery: Full leather</p>	<p>100€</p>



		<p>Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electric windows: Yes Electric seats: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Open roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports seats: Yes Seat heating: Yes Certificate of registration: Not present, see additional information Certificate of conformity: Not present, see additional information Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: Car is poorly wrapped, viewing is recommended. Only German documents.</p> <p>condition: Used Quantity: 1</p>	
	10	<p>Brand: VOLKSWAGEN Model: ID4 PURE Version: PERFORMANCE Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 28/02/2022 Fuel: Electric Read odometer reading (km): 13048 Chassis number: WVGZZZE2ZNP030031 Number of keys: 2 Vehicle category: M1: passenger car Type of car: Break / station wagon</p>	100€




		<p>Transmission: Automatic transmission Engine power kW: 125 Exterior colour: Blue Metal Color: Yes Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat heating: Yes Other options: heated steering wheel DAB tuner Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: rear flank damage condition: Used Quantity: 1</p>	
	<p>11</p>	<p>Make: MERCEDES BENZ Model: A180 Execution: D Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 28/11/2018 Fuel: Diesel Odometer reading (km): 139712 Chassis number: WDD1770031J016427 Number of keys: 2</p>	<p>100€</p>




		<p>Vehicle category: M1: passenger car Type of car: Berline Transmission: Automatic transmission Cylinder capacity cc: 1461 Engine power kW: 85 Emission class: Euro 6 Exterior colour: Silver Metal Color: Yes Interior color: Black Upholstery: Partial leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports seats: Yes Seat heating: Yes Certificate of registration: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 12/01/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	
--	--	---	--




	13	<p>Brand: FORD Model: MONDEO Year of construction (yyyy): 2001 First registration (dd/mm/yyyy): 07/06/2001 Fuel gasoline Read odometer reading (kms): 80969 Chassis number: WF04XXGGB41M72542 Number of keys: 1 Vehicle category: M1: passenger car Type of car: Berline Transmission: Manual transmission Cylinder capacity cc: 1798 Engine power kW: 92 Emission class: Euro 3 Color exterior: Gray Metal Color: No Interior color: Black Upholstery: Full leather Air conditioning: Fully automatic air conditioning Central locking: Yes Cruise Control: Yes Electric windows: Yes Electric seats: Yes Multifunctional steering wheel: Yes Open roof: Yes Radio: Yes Seat heating: Yes Additional information: start with booster! Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 02/11/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: start with booster! condition: Used Quantity: 1</p>	100€
---	----	---	------



	14	<p>Brand: FORD Model: FOCUS Year of manufacture (yyyy): 2006 First registration (dd/mm/yyyy): 25/01/2006 Fuel: Diesel Read odometer reading (km's): 214566 Chassis number: WF05XXGCD56L89953 Number of keys: 1 Vehicle category: M1: passenger car Type of car: Berline Transmission: Manual transmission Cylinder capacity cc: 1560 Engine power kW: 66 Emission class: Euro 4 Color exterior: Gray Metal Color: No Color interior: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Radio: Yes Additional information: vehicle does not start! fuel leak at the injector engine failure Certificate of registration: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: vehicle will not start! fuel leak at the injector engine failure condition: Used Quantity: 1</p>	100€
---	----	---	------




	15	<p>Brand: BMW Model: 520i Year of manufacture (yyyy): 1999 First registration (dd/mm/yyyy): 16/07/1999 Fuel gasoline Read odometer reading (kms): 195440 Chassis number: WBADM11060GP15010 Number of keys: 2 Vehicle category: M1: passenger car Type of car: Berline Transmission: Manual transmission Cylinder capacity cc: 1991 Engine power kW: 110 Exterior colour: Green Metal Color: No Color interior: Green Upholstery: Full leather Air conditioning: Manual air conditioning Central locking: Yes Cruise Control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Radio: Yes Additional information: start with booster! Certificate of registration: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 17/09/2021 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: start with booster! condition: Used Quantity: 1</p>	100€
---	----	--	------



	17	<p>Brand: VOLKSWAGEN Model: GOLF 3 Version: VR 6 Year of manufacture (yyyy): 1992 First registration (dd/mm/yyyy): 17/12/1992 Fuel gasoline Read odometer reading (km's): 37238 Chassis number: WVWZZZ1HZPW383891 Number of keys: 1 Vehicle category: M1: passenger car Type of car: Berline Transmission: Manual transmission Cylinder capacity cc: 2792 Engine power kW: 128 Exterior colour: White Metal Color: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Open roof: Yes Radio: Yes Additional information: customs document E705 present Austrian registration certificate present Certificate of registration: Yes, present Certificate of conformity: Not present. (Import within European Union) Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	100€
	18	<p>Brand: Audi Model: A4 Version: Convertible Year of construction (yyyy): 2007 First registration (dd/mm/yyyy): 05/09/2007 Fuel gasoline</p>	100€




		<p>Read odometer reading (kms): 177107 Chassis number: WAUZZZ8H68K005194 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Convertible Transmission: Manual transmission Cylinder capacity cc: 1781 Motor power kW: 120 Emission class: Euro 4 Color exterior: Gray Metal Color: No Interior color: Black Upholstery: Full leather Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Rear parking sensors: Yes Radio: Yes Seat heating: Yes Certificate of registration: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 20/04/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: various damages condition: Used Quantity: 1</p>	
	23	<p>Make: MERCEDES BENZ Model: A180 D Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 10/09/2018 Fuel: Diesel Odometer reading (km): 226308</p>	100€




		<p>Chassis number: WDD1770031N002559 Number of keys: 2 Vehicle category: M1: passenger car Type of car: Berline Transmission: Automatic transmission Cylinder capacity cc: 1461 Engine power kW: 85 Emission class: Euro 6 Color exterior: Gray Metal Color: No Interior color: Black Upholstery: Partial leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning Central locking: Yes Cruise Control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Sports seats: Yes Other options: AMG package Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 16/11/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	
--	--	--	--




	25	<p>Make: MERCEDES BENZ Model: C180 Version: BLUETEC Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 14/01/2016 Fuel: Diesel Odometer reading (km): 237036 Chassis number: WDD2050361R088715 Number of keys: 2 Vehicle category: M1: passenger car Type of car: Berline Transmission: Automatic transmission Cylinder capacity cc: 1598 Engine power kW: 85 Emission class: Euro 6 Exterior colour: Silver Metal Color: No Interior color: Black Upholstery: Full leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise Control: Yes Electric windows: Yes Alloy Wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports seats: Yes Additional information: starting with booster Certificate of registration: Yes, present Certificate of conformity: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 24/01/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: starting with booster condition: Used Quantity: 1</p>	100€
---	----	---	------




	27	<p>Brand: VOLVO Model: S90 Version: INSCRIPTION B4 MILD HYBRID Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 19/08/2021 Fuel gasoline Read odometer reading (km): 32434 Chassis number: LVYPSK9VDMP101124 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Engine capacity cc: 1969 Engine power kW: 145 Emission class: Euro 6 Exterior color: Blue Metallic colour: Yes Interior color: Brown Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat ventilation: Yes Seat heating: Yes Other options: electric seats with memory function steering wheel heating DAB tuner Metallic color 'DENIM BLUE'</p>	100€
---	----	---	------




		<p>Amber comfort seats with ventilated 'Nappa' leather 'Charcoal' headliner 'Pitched Oak' wood inlay Geartronic 8-speed automatic Additional information: Equipped with a set of 4 winter tires MICHELEN PILOT ALPIN 5 245/45 R18 100V Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	28	<p>Brand: FIAT Model: ABARTH Version: 595 Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 06/06/2018 Fuel gasoline Read odometer reading (kms): 71599 Chassis number: ZFA3120000J988693 Number of keys: 2 Vehicle category: M1: passenger car Type of car: City car Transmission: Manual transmission Cylinder capacity cc: 1368 Engine power kW: 99 Emission class: Euro 6b Color exterior: Gray Metal Color: No Color interior: Brown Upholstery: Full leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Electric windows: Yes Alloy Wheels: Yes</p>	100€




		<p>Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Open roof: Yes Rear parking sensors: Yes Radio: Yes Sports package: Yes Sports seats: Yes Other options: DAB tuner Certificate of registration: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 12/07/2024 Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	
	29	<p>Brand: FORD Model: GALAXY Year of construction (yyyy): 2007 First registration (dd/mm/yyyy): 16/04/2007 Fuel gasoline Read odometer reading (kms): 216753 Chassis number: WF0MXXGBWM6G66551 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Monovolume Transmission: Manual transmission Emission class: Euro 3 Color exterior: Gray Metal Color: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise Control: Yes Electric windows: Yes Fog lights: Yes</p>	100€



		<p>Multifunctional steering wheel: Yes Radio: Yes Towbar: Yes Other options: 7 seats Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Not present: the buyer receives a certificate of loss of conformity certificate CARPASS: Yes, present Test certificate: Yes, present Test certificate valid until (dd/mm/yyyy):: 21/08/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	
	40	<p>Brand: PEUGEOT Model: 807 Year of construction (yyyy): 2008 First registration (dd/mm/yyyy): 07/10/2008 Fuel: Diesel Read odometer reading (km): unknown Chassis number: VF3EBRHKH13390505 Number of keys: 0 Vehicle category: M1: passenger car Car type: Monovolume Transmission: Manual transmission Engine capacity cc: 1997 Engine power kW: 88 Emission class: Euro 4 Exterior color: Gray Metallic colour: No Interior color: Gray Upholstery: Fabric Air conditioning: Fully automatic air conditioning Central locking: Yes Cruise control: Yes</p>	10€



		<p>Electric windows: Yes Radio: Yes Towbar: Yes Additional information: without key!</p> <p>Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 24/08/2021 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: without key, vehicle does not drive! flat tire condition: Used Quantity: 1</p>	
	46	<p>Brand: OPEL Model: ZAFIRA Version: TOURER Year of manufacture (yyyy): 2015 First registration (dd/mm/yyyy): 27/11/2015 Fuel: Diesel Odometer reading (km): 231031 Chassis number: W0LPD9E34G1006302 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Monovolume Transmission: Manual transmission Cylinder capacity cc: 1598 Emission class: Euro 6 Exterior colour: White Metal Color: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning</p>	100€



		<p>On-board computer: Yes Central locking: Yes Cruise Control: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Radio: Yes Seat heating: Yes Other options: including 4 winter tires on CONTINENTAL rim Additional information: German vehicle documents. Certificate of registration: Yes, present Certificate of conformity: Not present. (Import within European Union) Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	
--	--	--	--