

CATALOG COMMERCIAL VEHICLES



DESCRIPTION

Auction of various commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

3 october 2023 to 08:00 [UTC]

END DATE

10 october 2023 from 17:00 [UTC]

VIEWING

- Wednesday October 04 2023 from 15:00 until 17:00
Helststraat 47, 2630 Aartselaar

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452 153 622



ISSUE - COLLECTION

- Wednesday October 18 2023 from 10:00 until 12:00
Helststraat 47, 2630 Aartselaar


Online bidding only!

Catalog created on 10 october 2023 to 04:01




	Item	Description	Start price
	1	<p>Sell yourself? Click here!</p> <p>Via online auctions on the Auctim platform you immediately get value for your money. Or better, money for your money!</p> <ul style="list-style-type: none">• Our partners look at the possibilities together with you• You benefit from an extensive, worldwide marketing campaign• Reach a buying audience from over 150 countries with millions of page views every month• You will receive the proceeds from your lots barely 20 days after the auction. <p>(Almost) convinced? Click here!</p>	1€
	4	<p>Brand: VOLKSWAGEN Model: CADDY Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 03/04/2019 Fuel gasoline Read odometer reading (km): 56586 Chassis number: WV1ZZZ2KZKX061005 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 2034 Transmission: Manual transmission Cylinder capacity cc: 1197 Engine power kW: 62 Emission class: Euro 6b Co2 emissions g/km: 137 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning</p>	100€




		<p>Central locking: Yes Electric windows: Yes Additional information: no radio available! Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 13/06/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: demolition of bodywork condition: Used Quantity: 1</p>	
	6	<p>Brand: FIAT Model: DUCATO Version: 130 MULTIJET Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 25/07/2016 Fuel: Diesel Read odometer reading (km): 118864 Chassis number: ZFA25000002B01168 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2287 Engine power kW: 96 Emission class: Euro 5b Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes</p>	100€




		<p>Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Radio: Yes Tow bar: Yes Other options: roof rack ladder Additional information: including content Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 04/11/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: sliding door handle missing various damages: rear light, damaged bodywork, driver's seat, etc. condition: Used Quantity: 1</p>	
	7	<p>Brand: FIAT Model: DUCATO Version: 130 MULTIJET Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 13/04/2016 Fuel: Diesel Read odometer reading (km): 97760 Chassis number: ZFA25000002A73135 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2287</p>	100€



		<p>Engine power kW: 96 Emission class: Euro 5b Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 05/11/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damage: side mirrors, bumpers, dents and scratches on the bodywork. condition: Used Quantity: 1</p>	
	8	<p>Brand: FIAT Model: DUCATO Version: 130 MULTIJET Year of construction (yyyy): 2015 First registration (dd/mm/yyyy): 02/06/2015 Fuel: Diesel Read odometer reading (km): 134659 Chassis number: ZFA25000002861894 Number of keys: 1 Vehicle category: N1: max. mass <3.5t.</p>	100€




		<p>Construction: Closed van Number of axles: 2 Maximum Authorized Mass (kg): 2015 Transmission: Manual transmission Cylinder capacity cc: 2287 Engine power kW: 96 Emission class: Euro 5b Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Radio: Yes Towbar: Yes Additional information: including remaining contents Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 10/11/2023 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damage: side mirror, rear light, bodywork, driver's seat condition: Used Quantity: 1</p>	
	10	<p>Brand: MERCEDES-BENZ Model: VITO Version: 116 CDI Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 22/11/2017 Fuel: Diesel Read odometer reading (km): 219457</p>	100€




Chassis number: WDF44770313371299
Number of keys: 1
Vehicle category: N1: max. mass <3.5t.
Construction: van with double cabin
Number of axles: 2
Maximum Allowable Mass (kg): 3050
Transmission: Automatic transmission
Cylinder capacity cc: 2143
Engine power kW: 120
Emission class: Euro 6b
Co2 emissions g/km: 176
Exterior color: Gray
Metallic colour: No
Interior color: Black
Upholstery: Artificial leather
Reversing camera: Yes
Air conditioning: Manual air conditioning
On-board computer: Yes
Central locking: Yes
Cruise control: Yes
Electrically folding mirrors: Yes
Electric windows: Yes
Fog lights: Yes
Multifunctional steering wheel: Yes
Navigation: Yes
Rear parking sensors: Yes
Radio: Yes
Paddle shifters: Yes
Towbar: Yes
Registration certificate: Yes, available
Certificate of conformity: Yes, available
Identification report: Yes, present
Inspection certificate: Yes, available
Inspection certificate valid until (dd/mm/yyyy)::
23/11/2023
Maintenance booklet: Not present
Visible vehicle damage: Yes, for a detailed
overview of the visible damage you can always
consult the photo report.
condition: Used
Quantity: 1




	11	<p>Brand: FIAT Model: DUCATO MAXI Version: 2.3 130 Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 31/08/2018 Fuel: Diesel Read odometer reading (km): 86127 Chassis number: ZFA25000002H24406 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3300 Transmission: Manual transmission Cylinder capacity cc: 2287 Engine power kW: 96 Emission class: Euro 6 Co2 emissions g/km: 173 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Electric windows: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: roof rack Additional information: including contents including various screws and plugs HILTI, WÜRTH etc. Certificate of registration: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: driver's seat bodywork damage</p>	100€
---	----	---	------




		condition: Used Quantity: 1	
	12	Brand: FIAT Model: DOBLO Version: 90 MULTIJET Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 31/05/2016 Fuel: Diesel Read odometer reading (km): 108108 Chassis number: ZFA26300006C24027 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 2420 Transmission: Manual transmission Cylinder capacity cc: 1248 Engine power kW: 66 Emission class: Euro 5b Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Towbar: Yes Other options: DAB tuner Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 27/11/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.	100€



		Vehicle damage description: various bodywork damage! condition: Used Quantity: 1	
	16	Brand: FIAT Model: DUCATO MAXI SERIES 8 Version: L3H2 MULTIJET 3 140 Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 07/12/2021 Fuel: Diesel Read odometer reading (km): 19867 Chassis number: ZFA25000002U03727 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2184 Engine power kW: 103 Emission class: Euro 6 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Radio: Yes Other options: DAB tuner ladder roof rack Additional information: including content Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity	100€




		<p>Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	17	<p>Brand: FIAT Model: DUCATO Version: 2.3 120 Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 26/02/2021 Fuel: Diesel Read odometer reading (km): 42851 Chassis number: ZFA25000002S04865 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2287 Engine power kW: 88 Emission class: Euro 6 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Radio: Yes Tow bar: Yes Other options: DAB tuner roof rack ladder Additional information: including contents including various screws and plugs WÜRTH, 2</p>	100€




		<p>empty systainers FESTOOL containing various hand tools, transport trolley, etc. Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 19/03/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: rear bumper minor bodywork damage condition: Used Quantity: 1</p>	
	18	<p>Brand: PEUGEOT Model: BOXER Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 24/07/2013 Fuel: Diesel Read odometer reading (km): 197639 Chassis number: VF3YDUMAU12305439 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: box truck Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 110 Emission class: Euro 5 Co2 emissions g/km: 229 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Central locking: Yes Electric windows: Yes</p>	100€




		<p>Fog lights: Yes Radio: Yes Towbar: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 03/11/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages driver's seat condition: Used Quantity: 1</p>	
	19	<p>Brand: PEUGEOT Model: BOXER Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 26/08/2016 Fuel: Diesel Read odometer reading (km): 112778 Chassis number: VF3YCTMFC12A73040 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 96 Emission class: Euro 5b Co2 emissions g/km: 195 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning Central locking: Yes</p>	100€




		<p>Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Towbar: Yes Other options: roof rack ladder Additional information: including contents including various screws and plugs WÜRTH Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 06/02/2024 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damage to bodywork, side mirror, etc. rear door is stuck, side door does not open condition: Used Quantity: 1</p>	
	20	<p>Brand: FIAT Model: DUCATO Version: MAXI 2.3 130 Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 17/12/2019 Fuel: Diesel Read odometer reading (km): 75956 Chassis number: ZFA25000002K33959 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2287 Engine power kW: 96</p>	100€




		<p>Emission class: Euro 6b Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Radio: Yes Tow bar: Yes Other options: roof rack ladder Additional information: including contents including screws and plugs WÜRTH Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 20/12/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: broken hood front bumper damage condition: Used Quantity: 1</p>	
	23	<p>Brand: MERCEDES-BENZ Model: VITO Version: 114 CDI Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 07/11/2017 Fuel: Diesel Read odometer reading (km): 212100 Chassis number: WDF44770313369717</p>	10€




		<p>Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: van with double cabin Number of axles: 2 Maximum Allowable Mass (kg): 2800 Transmission: Manual transmission Cylinder capacity cc: 2143 Engine power kW: 100 Emission class: Euro 6b Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Radio: Yes Additional information: start with booster! Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 03/12/2022 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! vehicle won't start without booster! dashboard engine light condition: Used Quantity: 1</p>	
	24	<p>Brand: MERCEDES-BENZ Model: VITO Version: 114 CDI Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 07/11/2017 Fuel: Diesel</p>	10€




		<p>Read odometer reading (km): 211877 Chassis number: WDF44770313367515 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: van with double cabin Number of axles: 2 Maximum Allowable Mass (kg): 2800 Transmission: Manual transmission Cylinder capacity cc: 2143 Engine power kW: 100 Emission class: Euro 6b Co2 emissions g/km: 182 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 09/11/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: flat tire in the front! various notifications dashboard condition: Used Quantity: 1</p>	
	24	<p>Brand: CITROËN Model: BERLINGO Version: M LIGHT 1.5 BLUEHDI Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 28/11/2020</p>	100€



		<p>Fuel: Diesel Read odometer reading (km): 41760 Chassis number: VR7EFYHWCLN511579 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Transmission: Manual transmission Cylinder capacity cc: 1499 Engine power kW: 55 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Radio: Yes Additional information: Fuel level very low Certificate of registration: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damage: side flank, etc. condition: Used Quantity: 1</p>	
	25	<p>Brand: PEUGEOT Model: PARTNER Year of construction (yyyy): 2015 First registration (dd/mm/yyyy): 20/03/2015 Fuel: Diesel Read odometer reading (km): 307837 Chassis number: VF37A9HN0EN550817 Number of keys: 1</p>	100€




		<p>Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Authorized Mass (kg): 1935 Transmission: Manual transmission Cylinder capacity cc: 1560 Engine power kW: 55 Emission class: Euro 5b Exterior color: Gray Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Radio: Yes Additional information: start with booster! Certificate of registration: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 25/01/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: starting with booster - battery defective! various damages!! notification dashboard condition: Used Quantity: 1</p>	
	26	<p>Brand: MERCEDES-BENZ Model: V250D Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 23/08/2019 Fuel: Diesel Read odometer reading (km): 99841 Chassis number: WDF44781313566599 Number of keys: 2</p>	100€




		<p>Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3100 Transmission: Automatic transmission Cylinder capacity cc: 2143 Engine power kW: 140 Emission class: Euro 6 Exterior color: Gray Metallic colour: Yes Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes LED lighting: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Paddle shifters: Yes Tow bar: Yes Seat heating: Yes Other options: DAB tuner seat ventilation electric seats with memory function electric sliding door BURMESTER sound system Additional information: 5 seats Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 29/08/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed</p>	
--	--	--	--




		overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1	
	27	Brand: RENAULT Model: TRAFIC Year of construction (yyyy): 2009 First registration (dd/mm/yyyy): 19/11/2009 Fuel: Diesel Read odometer reading (km): 248767 Chassis number: VF1FLBMB6AV360248 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 2960 Transmission: Manual transmission Engine capacity cc: 1995 Engine power kW: 66 Emission class: Euro 4 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Electric windows: Yes Radio: Yes Tow bar: Yes Other options: roof rack MTS Additional information: start with booster! starts difficult Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 30/04/2022 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster!	10€




		starts difficult various damages condition: Used Quantity: 1	
	28	Brand: IVECO Model: 50C/35 Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 27/02/2013 Fuel: Diesel Read odometer reading (km): 175113 Chassis number: ZCFC50A4005931227 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: box truck Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2998 Engine power kW: 107 Emission class: Euro 5 Co2 emissions g/km: 256 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Radio: Yes Other options: equipped with D'HOLLANDIA tailgate with key Additional information: starting with booster - battery defective! Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 12/10/2023	100€




		<p>Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: starting with booster - battery defective! dashboard notifications: EDC, engine condition: Used Quantity: 1</p>	
	36	<p>Make: MERCEDES BENZ Model: VITO Version: 114 CDI Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 15/03/2018 Fuel: Diesel Read odometer reading (kms): 203953 Chassis number: WDF44770313379796 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowed Mass (kg): 2800 Transmission: Manual transmission Cylinder capacity cc: 2143 Motor power kW: 100 Emission class: Euro 6b Co2 emissions gr/km: 182 Color exterior: Gray Metal Color: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Radio: Yes Towbar: Yes Additional information: Vehicle does not start! Certificate of registration: Yes, present Certificate of conformity: Not present: the buyer receives a certificate of loss of conformity certificate</p>	100€



		<p>Test certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Vehicle damage description: Vehicle won't start! condition: Used Quantity: 1</p>	
	37	<p>Make: MERCEDES BENZ Model: VITO Version: 111 CDI Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 04/10/2017 Fuel: Diesel Read odometer reading (km): 208993 Chassis number: WDF447603H3262295 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowed Mass (kg): 2800 Transmission: Manual transmission Cylinder capacity cc: 1598 Engine power kW: 84 Emission class: Euro 6 Exterior colour: Blue Metal Color: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Fog lights: Yes Radio: Yes Certificate of registration: Not present: the buyer receives a certificate of loss of registration certificate Certificate of conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Test certificate: Yes, present</p>	100€



		<p>Test certificate valid until (dd/mm/yyyy):: 29/06/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. condition: Used Quantity: 1</p>	
	39	<p>Brand: FIAT Model: DUCATO Version: 150 MULTIJET Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 04/01/2012 Fuel: Diesel Read odometer reading (km): unknown Chassis number: ZFA25000002123003 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3300 Transmission: Manual transmission Cylinder capacity cc: 2287 Engine power kW: 109 Emission class: Euro 5 Co2 emissions g/km: 189 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Additional information: vehicle is sold as a wreck, the buyer is responsible for the certificates of loss. Registration certificate: Yes, available Certificate of conformity: Not present, see additional information Inspection certificate: Not applicable Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: vehicle is sold as a</p>	10€



		wreck, the buyer is responsible for the certificates of loss. Do not start!! condition: Used Quantity: 1	
--	--	---	--