

## CATALOG

### Passenger cars



#### DESCRIPTION

Auction of passenger cars from various bankruptcies, seizures, breaches of contract, etc.

#### START

16 march 2024 to 09:00 [UTC]

#### END DATE

26 march 2024 from 13:00 [UTC]

#### VIEWING

- Wednesday March 20 2024 from 15:00 until 17:00  
Helststraat 47, 2630 Aartselaar

#### AUCTIM PARTNER

##### MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium  
+32 3 827 21 31 - [info.moyersoen@auctim.be](mailto:info.moyersoen@auctim.be)  
BTW BE 0452 153 622


#### ISSUE - COLLECTION

- Wednesday April 03 2024 from 10:00 until 17:00  
Helststraat 47, 2630 Aartselaar


**Online bidding only!**

Catalog created on 26 march 2024 to 04:00




	Item	Description	Start price
	3	<p>Brand: Mercedes-Benz Model: GLC 200D Version: 4 MATIC Coupé Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 31/05/2023 Fuel: Diesel Read odometer reading (km): 9882 Chassis number: W1N0J1GBXPG149827 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Automatic transmission Engine capacity cc: 1950 Engine power kW: 120 Emission class: Euro 6 Exterior color: Gray Metallic colour: No Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric tailgate: Yes Electric windows: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Paddle shifters: Yes Seat heating: Yes Other options: DAB tuner color: gray matt MBUX multimedia system exterior chrome package Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Not present</p>	100€




		Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview. condition: Used Quantity: 1	
	4	Brand: Mercedes-Benz Model: E 200D Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 11/12/2017 Fuel: Diesel Read odometer reading (km): 330902 Chassis number: WDD2130131A351238 Number of keys: 1 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports seats: Yes	100€



		<p>Seat heating: Yes Other options: Burmester sound system electric seats with memory function Additional information: start with booster! without on-board documents Certificate of registration: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: starting with booster, battery defective! dashboard engine control notification! interior condition: Used Quantity: 1</p>	
	7	<p>Brand: Mazda Model: CX-5 Version: 2.0 Skyactiv-G Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 18/02/2019 Fuel gasoline Read odometer reading (km): 75064 Chassis number: JMZKF6W7600812457 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Manual transmission Engine capacity cc: 1998 Engine power kW: 120 Emission class: Euro 6 Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning</p>	100€




		<p>On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat heating: Yes Other options: steering wheel heating Certificate of registration: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 18/02/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: oil service required condition: Used Quantity: 1</p>	
	8	<p>Brand: Volvo Model: V60 Version: Inscription T6 Twin Engine Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 08/03/2019 Fuel: Hybrid - Electric/Gasoline Read odometer reading (km): 129460 Chassis number: YV1ZWBMUDK1331691 Number of keys: 2 Vehicle category: M1: passenger car Car type: Break / station wagon Transmission: Automatic transmission Engine capacity cc: 1969</p>	100€




Engine power kW: 223  
Emission class: Euro 6  
Exterior color: Blue  
Metallic colour: Yes  
Interior color: Beige  
Upholstery: Full leather  
Air conditioning: Fully automatic air conditioning  
On-board computer: Yes  
Central locking: Yes  
Cruise control: Yes  
Electrically folding mirrors: Yes  
Electric tailgate: Yes  
Electric windows: Yes  
Alloy wheels: Yes  
Fog lights: Yes  
Multifunctional steering wheel: Yes  
Navigation: Yes  
Sunroof: Yes  
Panoramic roof: Yes  
Rear parking sensors: Yes  
Front parking sensors: Yes  
Radio: Yes  
Tow bar: Yes  
Other options: Electrically folding tow bar  
Additional information: Equipped with charging cable  
Certificate of registration: Not present: the buyer will receive a certificate of loss of registration certificate  
Certificate of conformity: Yes, available  
Inspection certificate: Yes, available  
Inspection certificate valid until (dd/mm/yyyy):: 08/03/2024  
Maintenance booklet: Not present  
Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.  
Vehicle damage description: Electrically folding tow bar defective  
various damages  
condition: Used  
Quantity: 1



	9	<p>Brand: Mercedes-Benz Model: C220 Implementation: D Business Solution Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 07/01/2020 Fuel: Diesel Read odometer reading (km): 25324 Chassis number: WDD2050141R438773 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Engine capacity cc: 1950 Engine power kW: 143 Emission class: Euro 6 Exterior color: Silver Metallic colour: Yes Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Paddle shifters: Yes Seat heating: Yes Other options: DAB tuner Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 28/06/2024 Maintenance booklet: Not present Visible vehicle damage: No, with the exception of</p>	100€
---	---	--	------







		<p>general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview.</p> <p>condition: Used</p> <p>Quantity: 1</p>	
	12	<p>Brand: Ford</p> <p>Model: Galaxy</p> <p>Year of construction (yyyy): 2019</p> <p>First registration (dd/mm/yyyy): 29/03/2019</p> <p>Fuel: Diesel</p> <p>Read odometer reading (km): 141535</p> <p>Chassis number: WF0KXXWPCKJA16894</p> <p>Number of keys: 2</p> <p>Vehicle category: M1: passenger car</p> <p>Car type: Monovolume</p> <p>Transmission: Automatic transmission</p> <p>Engine capacity cc: 1995</p> <p>Engine power kW: 140</p> <p>Exterior color: Black</p> <p>Metallic colour: No</p> <p>Interior color: Black</p> <p>Upholstery: Fabric</p> <p>Reversing camera: Yes</p> <p>Air conditioning: Fully automatic air conditioning</p> <p>On-board computer: Yes</p> <p>Central locking: Yes</p> <p>Cruise control: Yes</p> <p>Electrically folding mirrors: Yes</p> <p>Electric windows: Yes</p> <p>Alloy wheels: Yes</p> <p>Fog lights: Yes</p> <p>Multifunctional steering wheel: Yes</p> <p>Navigation: Yes</p> <p>Rear parking sensors: Yes</p> <p>Front parking sensors: Yes</p> <p>Radio: Yes</p> <p>Towbar: Yes</p> <p>Seat heating: Yes</p> <p>Other options: 7 seats</p> <p>DAB tuner</p>	100€






		<p>Additional information: Provided with German registration certificate parts 1 + 2          Provided with customs document E705          Registration certificate: Yes, available          Certificate of Conformity: Not present. (Import within European Union)          Inspection certificate: Not present          Maintenance booklet: Not present          Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview.          condition: Used          Quantity: 1</p>	
	13	<p>Brand: BMW          Model: M550D          Year of construction (yyyy): 2013          First registration (dd/mm/yyyy): 25/07/2013          Fuel: Diesel          Read odometer reading (km): 173383          Chassis number: WBA5D91080D060935          Number of keys: 3          Vehicle category: M1: passenger car          Car type: Berline          Transmission: Automatic transmission          Cylinder capacity cc: 2993          Emission class: Euro 6          Exterior color: Blue          Metallic colour: Yes          Interior color: Beige          Upholstery: Full leather          Reversing camera: Yes          Air conditioning: Fully automatic air conditioning          On-board computer: Yes          Central locking: Yes          Cruise control: Yes          Electric tailgate: Yes          Electric windows: Yes          Electric seats: Yes          Alloy wheels: Yes</p>	100€



		<p>             Fog lights: Yes              Multifunctional steering wheel: Yes              Navigation: Yes              Sunroof: Yes              Panoramic roof: Yes              Rear parking sensors: Yes              Front parking sensors: Yes              Radio: Yes              Paddle shifters: Yes              Sports package: Yes              Other options: electric seats with memory function              M package           </p> <p>             Additional information: Provided with German registration certificate parts 1 + 2              Provided with customs document E705              Equipped with German Dekra inspection              Registration certificate: Yes, available              Certificate of Conformity: Not present. (Import within European Union)              Inspection certificate: Not present              Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.              Vehicle damage description: dashboard brake system reports              condition: Used              Quantity: 1           </p>	
	14	<p>             Brand: Audi              Model: Q3              Version: 35 TFSI              Year of construction (yyyy): 2018              First registration (dd/mm/yyyy): 19/02/2019              Fuel gasoline              Read odometer reading (km): 158266              Chassis number: WAUZZZF30K1008337              Number of keys: 2              Vehicle category: M1: passenger car              Vehicle type: SUV or 4x4              Transmission: Automatic transmission           </p>	100€




		<p>             Cylinder capacity cc: 1498              Engine power kW: 110              Emission class: Euro 6              Co2 emissions g/km: 163              Exterior color: Silver              Metallic colour: No              Interior color: Black              Upholstery: Partial leather              Air conditioning: Fully automatic air conditioning              On-board computer: Yes              Central locking: Yes              Cruise control: Yes              Electrically folding mirrors: Yes              Electric tailgate: Yes              Electric windows: Yes              Alloy wheels: Yes              Fog lights: Yes              Multifunctional steering wheel: Yes              Navigation: Yes              Rear parking sensors: Yes              Front parking sensors: Yes              Radio: Yes              Seat heating: Yes              Other options: DAB tuner              Registration certificate: Yes, available              Certificate of conformity: Yes, available              Inspection certificate: Yes, available              Inspection certificate valid until (dd/mm/yyyy)::              19/02/2024              Maintenance booklet: Not present              Visible vehicle damage: Yes, for a detailed              overview of the visible damage you can always              consult the photo report.              condition: Used              Quantity: 1           </p>	
	15	<p>             Brand: BMW              Model: X5              Version: S Drive 25D              Year of construction (yyyy): 2014              First registration (dd/mm/yyyy): 13/02/2014              Fuel: Diesel           </p>	100€




Read odometer reading (km): 149360  
Chassis number: WBAKS010200C46842  
Number of keys: 2  
Vehicle category: M1: passenger car  
Vehicle type: SUV or 4x4  
Transmission: Automatic transmission  
Engine capacity cc: 1995  
Engine power kW: 160  
Emission class: Euro 6b  
Co2 emissions g/km: 151  
Exterior color: Black  
Metallic colour: Yes  
Interior color: Black  
Upholstery: Full leather  
Reversing camera: Yes  
Air conditioning: Fully automatic air conditioning  
On-board computer: Yes  
Central locking: Yes  
Cruise control: Yes  
Electrically folding mirrors: Yes  
Electric tailgate: Yes  
Electric windows: Yes  
Electric seats: Yes  
Alloy wheels: Yes  
Fog lights: Yes  
Multifunctional steering wheel: Yes  
Navigation: Yes  
Rear parking sensors: Yes  
Radio: Yes  
Paddle shifters: Yes  
Sports package: Yes  
Seat heating: Yes  
Other options: M package  
electric seats with memory function  
Registration certificate: Yes, available  
Certificate of conformity: Yes, available  
CARPASS: Yes, present  
Inspection certificate: Yes, available  
Inspection certificate valid until (dd/mm/yyyy)::  
08/03/2024  
Maintenance booklet: Not present  
Visible vehicle damage: Yes, for a detailed  
overview of the visible damage you can always  
consult the photo report.  
Vehicle damage description: various damages




		condition: Used Quantity: 1	
	16	<p>Brand: Citroen Model: C3 Picasso Year of construction (yyyy): 2010 First registration (dd/mm/yyyy): 17/02/2010 Fuel gasoline Read odometer reading (km): 86607 Chassis number: VF7SCKFTA09A202989 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Manual transmission Cylinder capacity cc: 1360 Engine power kW: 54 Emission class: Euro 5 Co2 emissions g/km: 140 Exterior color: Gray Metallic colour: Yes Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 17/02/2024 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	100€




	26	<p>Brand: Ssangyong Model: Rexton Version: RX270 XVT Year of construction (yyyy): 2010 First registration (dd/mm/yyyy): 24/03/2010 Fuel: Diesel Read odometer reading (km): 273485 Chassis number: KPTG0C1FS7P251936 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Automatic transmission Cylinder capacity cc: 2696 Engine power kW: 137 Emission class: Euro 4 Co2 emissions g/km: 233 Exterior color: Gray Metallic colour: No Interior color: Black Upholstery: Full leather Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Towbar: Yes Seat heating: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 27/02/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p>	100€
---	----	---	------




		condition: Used Quantity: 1	
	30	Brand: Skoda Model: Octavia Version: TDI Year of construction (yyyy): 2013 First registration (dd/mm/yyyy): 23/04/2013 Fuel: Diesel Read odometer reading (km): 164241 Chassis number: TMBHT21Z8D2134848 Number of keys: 1 Vehicle category: M1: passenger car Car type: Break / station wagon Transmission: Manual transmission Cylinder capacity cc: 1598 Engine power kW: 77 Emission class: Euro 5 Co2 emissions g/km: 172 Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: Tinted rear windows Roof rails Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy)::	100€






		27/05/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Various scratches + damage to the rear condition: Used Quantity: 1	
	35	Brand: Opel Model: Crossland Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 09/07/2018 Fuel: Diesel Read odometer reading (km): 134548 Chassis number: W0V7D9EC0J4371881 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Manual transmission Cylinder capacity cc: 1560 Engine power kW: 73 Emission class: Euro 6b Exterior color: Gray Metallic colour: Yes Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Inspection certificate: Yes, available	100€



		<p>Inspection certificate valid until (dd/mm/yyyy):: 31/03/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	36	<p>Brand: Renault Model: Espace Version: Initiale Paris DCI 160 EDC Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 11/07/2018 Fuel: Diesel Read odometer reading (km): 109514 Chassis number: VF1RFC00359695986 Number of keys: 2 Vehicle category: M1: passenger car Car type: Monovolume Transmission: Automatic transmission Cylinder capacity cc: 1598 Engine power kW: 118 Emission class: Euro 6b Co2 emissions g/km: 120 Exterior color: White Metallic colour: No Interior color: Brown Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes</p>	100€




		<p>Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat ventilation: Yes Towbar: Yes Seat heating: Yes Other options: Initiale Paris package seat ventilation 4 control 7 seats Certificate of registration: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	46	<p>Brand: BMW Model: 116D Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 24/02/2020 Fuel: Diesel Read odometer reading (km): 187730 Chassis number: WBA7M710007F54561 Number of keys: 3 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Cylinder capacity cc: 1496 Engine power kW: 85 Emission class: Euro 6 Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Full leather Air conditioning: Fully automatic air conditioning</p>	100€




		<p>On-board computer: Yes  Central locking: Yes  Cruise control: Yes  Electrically folding mirrors: Yes  Electric windows: Yes  Alloy wheels: Yes  Fog lights: Yes  Multifunctional steering wheel: Yes  Navigation: Yes  Sunroof: Yes  Panoramic roof: Yes  Rear parking sensors: Yes  Radio: Yes  Other options: M package  Registration certificate: Yes, available  Certificate of conformity: Yes, available  Inspection certificate: Not present  Maintenance booklet: Not present  Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.  condition: Used  Quantity: 1</p>	
	52	<p>Brand: Skoda  Model: Fabia  Year of construction (yyyy): 2012  First registration (dd/mm/yyyy): 10/12/2012  Fuel gasoline  Read odometer reading (km): 191722  Chassis number: TMBPW46YX64466568  Number of keys: 2  Vehicle category: M1: passenger car  Car type: Berline  Transmission: Manual transmission  Cylinder capacity cc: 1198  Engine power kW: 40  Emission class: Euro 4  Co2 emissions g/km: 142  Exterior color: Black  Metallic colour: No  Interior color: Gray</p>	100€




		<p>Upholstery: Fabric Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 19/11/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: dashboard engine control report suitcase does not open various damages condition: Used Quantity: 1</p>	
	53	<p>Brand: Renault Model: Clio Version: 1.4 16V Year of construction (yyyy): 2000 First registration (dd/mm/yyyy): 26/10/2000 Fuel gasoline Read odometer reading (km): 107843 Chassis number: VF1CB0A0F23248244 Number of keys: 1 Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Cylinder capacity cc: 1149 Engine power kW: 43 Exterior color: Blue Metallic colour: No Interior color: Gray Upholstery: Fabric Electric windows: Yes Radio: Yes Additional information: start with booster!</p> <p>including remaining contents Registration certificate: Yes, available</p>	10€





		<p>Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 21/10/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! various damages condition: Used Quantity: 1</p>	
	54	<p>Brand: Peugeot Model: 207 Year of construction (yyyy): 2009 First registration (dd/mm/yyyy): 09/11/2009 Fuel gasoline Read odometer reading (km): 117335 Chassis number: VF3WCKFT09W099831 Number of keys: 1 Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Cylinder capacity cc: 1360 Engine power kW: 54 Emission class: Euro 5 Exterior color: Red Metallic colour: No Interior color: Gray Upholstery: Fabric Electric windows: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 09/01/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always</p>	100€




		consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1	
	55	Brand: Peugeot Model: 206+ Year of construction (yyyy): 2010 First registration (dd/mm/yyyy): 03/02/2010 Fuel gasoline Read odometer reading (km): 105273 Chassis number: VF32MKFWAAY019205 Number of keys: 2 Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Cylinder capacity cc: 1360 Engine power kW: 55 Emission class: Euro 4 Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 10/10/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1	100€





	57	<p>Brand: Suzuki Model: Alto Year of construction (yyyy): 2001 First registration (dd/mm/yyyy): 11/05/2001 Fuel gasoline Read odometer reading (km): 102094 Chassis number: MA3EFA12S00539980 Number of keys: 2 Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Cylinder capacity cc: 993 Engine power kW: 43 Emission class: Euro 3 Exterior color: Blue Metallic colour: No Interior color: Gray Upholstery: Fabric Electric windows: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 03/11/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	100€
	58	<p>Brand: Daewoo Model: Matiz Year of construction (yyyy): 2003 First registration (dd/mm/yyyy): 28/11/2003 Fuel gasoline Read odometer reading (km): 115644 Chassis number: KLA4M11CD4C929381 Number of keys: 1</p>	10€



		<p>Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Cylinder capacity cc: 796 Engine power kW: 38 Exterior color: Blue Metallic colour: No Interior color: Gray Upholstery: Fabric Electric windows: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 25/11/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	
	94	<p>Brand: Kia Model: Niro Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 17/04/2017 Fuel: Hybrid - Electric/Gasoline Read odometer reading (km): 221123 Chassis number: KNACC81CGH5024763 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Cylinder capacity cc: 1580 Engine power kW: 77.20 Emission class: Euro 6b Co2 emissions g/km: 101 Exterior color: Blue Metallic colour: Yes Interior color: Black Upholstery: Full leather</p>	100€



		<p>Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat ventilation: Yes Seat heating: Yes Other options: DAB tuner electric seats with memory function steering wheel heating JBL sound system Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 17/04/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! dashboard engine check notification dirty interior condition: Used Quantity: 1</p>	
--	--	--	--