



**CATALOG**  
Passenger cars



**DESCRIPTION**

Auction of passenger cars from various bankruptcies, seizures, breaches of contract, etc.

**START**

6 april 2024 to 08:00 [UTC]

**END DATE**

17 april 2024 from 12:00 [UTC]

**VIEWING**

- ---  
Wednesday April 10 2024 from 15:00 until 17:00  
Helststraat 47, 2630 Aartselaar

**AUCTIM PARTNER**

**MOYERSOEN NV**  
Helststraat 47, 2630 Aartselaar, Belgium  
+32 3 827 21 31 - info.moyersoен@auctim.be  
BTW BE 0452 153 622


**ISSUE - COLLECTION**

- ---  
Wednesday April 24 2024 from 10:00 until 12:00  
Helststraat 47, 2630 Aartselaar


**Online bidding only!**

Catalog created on 17 april 2024 to 04:00




	Item	Description	Start price
	1	<p>Brand: BMW Model: E92 320i Version: Convertible Year of construction (yyyy): 2007 First registration (dd/mm/yyyy): / Fuel gasoline Read odometer reading (km): 183129 Chassis number: WBAWK71060PX01027 Number of keys: 1 Vehicle category: M1: passenger car Car type: Convertible Transmission: Manual transmission Engine capacity cc: 1995 Engine power kW: 125 Exterior color: Blue Metallic colour: Yes Interior color: Gray Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Sunroof: Yes Radio: Yes Additional information: Color: Monaco blue Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Front hood,</p> <p>condition: Used Quantity: 1</p>	100€




	2	<p>Brand: Audi Model: Q3 Version: Sportback S-Line 35 TDI S TRONIC Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 20/05/2020 Fuel: Diesel Read odometer reading (km): 96648 Chassis number: WAUZZZF34L1095287 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Automatic transmission Engine capacity cc: 1968 Engine power kW: 110 Emission class: Euro 6 Co2 emissions g/km: 124 Exterior color: Black Metallic colour: Yes Interior color: Brown Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Paddle shifters: Yes Sports package: Yes Seat heating: Yes</p>	100€
---	---	--	------




		<p>Other options: S-Line Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 20/05/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	4	<p>Brand: Audi Model: Q2 Version: TDI Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 03/02/2017 Fuel: Diesel Read odometer reading (km): 149476 Chassis number: WAUZZZGA4HA025390 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Manual transmission Cylinder capacity cc: 1598 Engine power kW: 85 Emission class: Euro 6b Co2 emissions g/km: 114 Exterior color: Black Metallic colour: Yes Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Alloy wheels: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes</p>	100€




		<p>Radio: Yes Other options: Virtual cockpit Certificate of registration: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	
	5	<p>Brand: BMW Model: 420i Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 24/03/2023 Fuel gasoline Read odometer reading (km): 15177 Chassis number: WBA11AT090CM82899 Number of keys: 2 Vehicle category: M1: passenger car Car type: Convertible Transmission: Automatic transmission Engine capacity cc: 1998 Engine power kW: 135 Emission class: Euro 6 Exterior color: Gray Metallic colour: No Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Electric seats: Yes</p>	100€



		<p>LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Paddle shifters: Yes Sports package: Yes Sports seats: Yes Seat ventilation: Yes Seat heating: Yes Other options: DAB tuner electric seats with memory function</p> <p>Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	8	<p>Brand: Mazda Model: CX-5 Version: 2.0 Skyactiv-G Premium Edition Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 18/02/2019 Fuel gasoline Read odometer reading (km): 55692 Chassis number: JMZKF6W7600815752 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Manual transmission Engine capacity cc: 1998 Engine power kW: 120 Emission class: Euro 6 Co2 emissions g/km: 168</p>	100€




		<p>Exterior color: Black Metallic colour: Yes Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat heating: Yes Other options: steering wheel heating Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 18/02/2025 Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview. condition: Used Quantity: 1</p>	
	13	<p>Brand: BMW Model: M550D Year of construction (yyyy): 2013 First registration (dd/mm/yyyy): 25/07/2013 Fuel: Diesel Read odometer reading (km): 173383 Chassis number: WBA5D91080D060935 Number of keys: 3 Vehicle category: M1: passenger car</p>	100€




		<p>Car type: Berline Transmission: Automatic transmission Cylinder capacity cc: 2993 Emission class: Euro 6 Exterior color: Blue Metallic colour: Yes Interior color: Beige Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Paddle shifters: Yes Sports package: Yes Other options: electric seats with memory function M package</p> <p>Additional information: Provided with German registration certificate parts 1 + 2 Provided with customs document E705 Equipped with German Dekra inspection Registration certificate: Yes, available Certificate of Conformity: Not present. (Import within European Union) Inspection certificate: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: dashboard brake system reports condition: Used</p>	
--	--	---	--






		Quantity: 1	
	51	<p>Brand: Audi Model: A4 Version: Avant Ultra TDI Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 17/07/2017 Fuel: Diesel Read odometer reading (km): 200626 Chassis number: WAUZZZF4XJA024939 Number of keys: 2 Vehicle category: M1: passenger car Car type: Break / station wagon Transmission: Automatic transmission Engine capacity cc: 1968 Engine power kW: 110 Emission class: Euro 6b Co2 emissions g/km: 102 Exterior color: Black Metallic colour: Yes Interior color: Black Upholstery: Full leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used</p>	100€




		Quantity: 1	
	59	<p>Brand: Opel Model: Vivaro Year of construction (yyyy): 2007 First registration (dd/mm/yyyy): 14/02/2007 Fuel: LPG + petrol Read odometer reading (km): 268740 Chassis number: W0LJ7ALA67V624657 Number of keys: 1 Vehicle category: M1: passenger car Car type: Break / station wagon Transmission: Manual transmission Engine capacity cc: 1998 Engine power kW: 86 Emission class: Euro 4 Exterior color: Blue Metallic colour: No Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Rear parking sensors: Yes Radio: Yes Other options: double cabin Additional information: Vehicle registered as M1 - Passenger car. Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 01/09/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages driver's seat condition: Used Quantity: 1</p>	100€




	61	<p>Brand: Peugeot Model: Partner Year of construction (yyyy): 2004 First registration (dd/mm/yyyy): 15/11/2004 Fuel: LPG + petrol Read odometer reading (km): 187839 Chassis number: VF3GJKFWB95112077 Number of keys: 1 Vehicle category: M1: passenger car Car type: Break / station wagon Transmission: Manual transmission Cylinder capacity cc: 1360 Engine power kW: 55 Emission class: Euro 3 Co2 emissions g/km: 176 Exterior color: Gray Metallic colour: No Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 28/03/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	100€
---	----	---	------



	63	<p>Brand: Mini Model: One Execution: D Year of construction (yyyy): 2013 First registration (dd/mm/yyyy): 22/04/2013 Fuel: Diesel Read odometer reading (km): 167058 Chassis number: WWMSW11070T464149 Number of keys: 1 Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Cylinder capacity cc: 1598 Engine power kW: 66 Emission class: Euro 5 Co2 emissions g/km: 99 Exterior color: Brown Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Alloy wheels: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Seat heating: Yes Additional information: vehicle wrapped Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 22/04/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	100€
---	----	---	------



	66	<p>Brand: Citroen Model: C4 Version: E HDI Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 10/08/2011 Fuel: Diesel Read odometer reading (km): 140251 Chassis number: VF7NC9HR8BY591560 Number of keys: 1 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Cylinder capacity cc: 1560 Engine power kW: 82 Emission class: Euro 5 Exterior color: Gray Metallic colour: No Interior color: Black Upholstery: Partial leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy wheels: Yes Massage chairs: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 23/03/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	100€
---	----	---	------



**AUCTIM**  
ONLINE AUCTIONS

--	--	--	--